



~~COFC~~

In re Patent of:

YASUDA, ET AL.

Appl. No.: 10/551,112

Filed: March 26, 2004

For: MICROMECHANICAL POTENTIAL  
SENSOR

U.S. Patent No.: 7,274,193 B2

Issued: September 25, 2007

Examiner: W. Benson

Group Art Unit: 2858

March 20, 2008

Commissioner for Patents  
P.O. Box 1450  
Alexandria, VA 22313-1450

Certificate  
MAR 25 2008  
of Correction

REQUEST FOR CERTIFICATE OF  
CORRECTION UNDER RULES 322 AND 323

Sir:

It is respectfully requested that a Certificate of Correction be issued by the Patent and Trademark Office due to errors which appear in the printed patent as a result of Patent and Trademark Office mistakes, and mistakes of a clerical, typographical, or minor character, which were not the fault of the Patent and Trademark Office. A Certificate of Correction form, in duplicate, is enclosed.

Accompanying this letter is a check for \$100.00 to cover the statutory fee for such Certificate of Correction.

03/24/2008 DEMMANU1 00000003 7274193

01 FC:1811

100.00 OP  
RECEIVED-USPTO  
JAN 11 1964

MAR 25 2008

Patentees' undersigned attorney may be reached in our Costa Mesa,  
California office by telephone at (714) 540-8700. All correspondence should continue to  
be directed to our address given below.

Respectfully submitted,



---

Edward A. Kmett  
Attorney for Patentees  
Registration No.: 42,746

FITZPATRICK, CELLA, HARPER & SCINTO  
30 Rockefeller Plaza  
New York, New York 10112-3800  
Facsimile: (212) 218-2200

FCHS\_WS 2005598v1

Staple  
Here  
Only!

PRINTER'S TRIM LINE

UNITED STATES PATENT AND TRADEMARK OFFICE  
**CERTIFICATE OF CORRECTION**

PATENT NO. : 7,274,193 B2

DATED : September 25, 2007

INVENTOR(S) : Yasuda, et al.

Page 1 of 1

It is certified that error appears in the above-identified patent and that said Letters Patent is hereby corrected as shown below:

COLUMN 5:

Line 29, "same" should read -- the same --.

COLUMN 6:

Line 3, "same" should read -- the same --.

COLUMN 9:

Line 30, "member" should read -- member is --; and

Line 39, "with in" should read -- within --.

COLUMN 10:

Line 1, "configure" should read -- configured --; and

Line 38, "include" should read -- includes --.

MAILING ADDRESS OF SENDER:

FITZPATRICK, CELLA, HARPER & SCINTO  
30 Rockefeller Plaza  
New York, New York 10112-3800  
(212) 218-2100 - Telephone  
(212) 218-2200 - Facsimile

PATENT NO. 7,274,193 B2

RECEIVED USPTO  
No. of add'l. copies  
@ 30¢ per page

MAR 25 2008  
➡

Staple  
Here  
Only!

PRINTER'S TRIM LINE

UNITED STATES PATENT AND TRADEMARK OFFICE  
**CERTIFICATE OF CORRECTION**

PATENT NO. : 7,274,193 B2

DATED : September 25, 2007

INVENTOR(S) : Yasuda, et al.

Page 1 of 1

It is certified that error appears in the above-identified patent and that said Letters Patent is hereby corrected as shown below:

COLUMN 5:

Line 29, "same" should read -- the same --.

COLUMN 6:

Line 3, "same" should read -- the same --.

COLUMN 9:

Line 30, "member" should read -- member is --; and

Line 39, "with in" should read -- within --.

COLUMN 10:

Line 1, "configure" should read -- configured --; and

Line 38, "include" should read -- includes --.

MAILING ADDRESS OF SENDER:

FITZPATRICK, CELLA, HARPER & SCINTO  
30 Rockefeller Plaza  
New York, New York 10112-3800  
(212) 218-2100 - Telephone  
(212) 218-2200 - Facsimile

PATENT NO. 7,274,193 B2

No. of add'l. copies  
@ 30¢ per page  
MAR 25 2008

